















Computer Uint (RXCU)


			
Ⓐ Base 1 PCS	Ⓑ Left Board 1 PCS	Ⓒ Right Board 1 PCS	Ⓓ Back Board 1 PCS
			
Ⓔ Top Cover 1 PCS	Ⓕ Round-head Screw 10 PCS	Ⓖ Flat-head Screw 8 PCS	Ⓗ Door with Holes 1 PCS
			
Ⓙ Sliding Shelf 1 PCS	Ⓚ Self-drilling screws 6 PCS	Ⓛ Keys 1 PCS	Overview Diagrams




STEP 1




STEP 2




STEP 3



STEP 4



STEP 5



STEP 6

